



SAFETY DATA SHEET

In accordance with REACH Regulation EC No.1907/2006

Product: Eastern Illusion INTENSE Candle - Wax Melt 478269CANDLE

Version: 1

Section 1. Identification of the substance or the mixture and of the supplier

1.1 Product Identifier

Product identifier: Eastern Illusion INTENSE Candle - Wax Melt 478269CANDLE

Other identifiers: None

1.2 Relevant identified uses of the substance or mixture and uses advised against

Product uses: AIRCARE

1.3 Details of the supplier of the safety data sheet

Company name: Scent Perfique Ltd

Company address: Unit 16/17 Castle Street
Castlepark Industrial Estate
Ellon
Aberdeenshire
AB41 9RF

Contact: Regulatory Affairs

E-Mail address: technical@scentperfique.co.uk

Company phone: +44 (0) 1358 720443

1.4 Emergency telephone number

Emergency phone: +44 (0) 1358 720443

Section 2. Hazards identification

2.1 Classification of the substance or mixture

Classification under Regulation (EC) No 1272/2008

Class and category of danger: Hazardous to the Aquatic Environment - Long-term Hazard Category 3
H412, Harmful to aquatic life with long lasting effects.

2.2 Label elements

Signal word: None

Hazard statements: H412, Harmful to aquatic life with long lasting effects.

Supplemental Information: EUH208, Contains 1-(1,2,3,4,5,6,7,8-Octahydro-2,3,8,8-tetramethyl-2-naphthalenyl)ethanone, 4-tert-Butylcyclohexyl acetate, Coumarin, d-Limonene, dl-Citronellol. May produce an allergic reaction.

Precautionary statements: P273, Avoid release to the environment.
P501, Dispose of contents/container to approved disposal site, in accordance with local regulations.

Pictograms: None

SAFETY DATA SHEET

In accordance with REACH Regulation EC No.1907/2006

Product: Eastern Illusion INTENSE Candle - Wax Melt 478269CANDLE

Version: 1

Other hazards: None

Section 3. Composition / information on ingredients

3.2 Mixtures

Contains:

Name	CAS	EC	REACH Registration No.	%	Classification for (CLP) 1272/2008
4-tert-Butylcyclohexyl acetate	32210-23-4	250-954-9		0.1-<1%	SS 1B;H317,-
1-(1,2,3,4,5,6,7,8-Octahydro-2,3,8,8-tetramethyl-2-naphthalenyl)ethanone	54464-57-2	259-174-3		0.1-<1%	SCI 2-SS 1B-EH C1; H315-H317-H410,-
2-Ethyl-4-(2,2,3-trimethyl-3-cyclopenten-1-yl)-2-buten-1-ol	28219-61-6	248-908-8		0.1-<1%	EDI 2-EH A1-EH C1; H319-H410,-
1,3,4,6,7,8-Hexahydro-4,6,6,7,8,8-hexamethylcyclopenta-gamma-2-benzopyran	1222-05-5	214-946-9		0.1-<1%	EH A1-EH C1;H410,-
d-Limonene	5989-27-5	227-813-5		0.1-<1%	FL 3-SCI 2-SS 1B-AH 1-EH A1-EH C1;H226-H304-H315-H317-H410,-
Coumarin	91-64-5	202-086-7		0.1-<1%	ATO 4-SS 1B;H302-H317,-
dl-Citronellol	106-22-9	203-375-0		0.1-<1%	SCI 2-EDI 2-SS 1B; H315-H317-H319,-
6-Acetyl-1,1,2,4,4,7-hexamethyltetraline	21145-77-7	244-240-6		0.1-<1%	ATO 4-EH A1-EH C1; H302-H410,-
alpha-Cedrene	469-61-4	207-418-4		<0.1%	AH 1-EH A1-EH C1; H304-H410,-
beta-Pinene	127-91-3	204-872-5		<0.1%	FL 3-SCI 2-SS 1B-AH 1-EH A1-EH C1;H226-H304-H315-H317-H410,-
p-Mentha-1,4-diene	99-85-4	202-794-6		<0.1%	FL 3-AH 1;H226-H304,-
alpha-Guaiene	3691-12-1			<0.1%	SCI 2-EDI 2-AH 1; H304-H315-H319,-
alpha-Pinene	80-56-8	201-291-9		<0.1%	FL 3-SCI 2-SS 1B-AH 1-EH A1-EH C1;H226-H304-H315-H317-H410,-
beta-Cedrene	546-28-1	208-898-8		<0.1%	AH 1-EH A1-EH C1; H304-H410,-
beta-Caryophyllene	87-44-5	201-746-1		<0.1%	SS 1B-AH 1;H304-H317,-
Myrcene	123-35-3	204-622-5		<0.1%	FL 3-SCI 2-EDI 2-AH 1; H226-H304-H315-H319,-
beta-Farnesene	18794-84-8	242-582-0		<0.1%	AH 1;H304,-
delta-3-Carene	13466-78-9	236-719-3		<0.1%	FL 3-SCI 2-SS 1B-AH 1;H226-H304-H315-H317,-
dl-Limonene (racemic)	138-86-3	205-341-0		<0.1%	FL 3-SCI 2-SS 1B-AH 1-EH A1-EH C1;H226-H304-H315-H317-H410,-

SAFETY DATA SHEET

In accordance with REACH Regulation EC No.1907/2006

Product: Eastern Illusion INTENSE Candle - Wax Melt 478269CANDLE

Version: 1

p-Cymene	99-87-6	202-796-7		<0.1%	FL 3-AH 1-EH C2; H226-H304-H411,-
Bisabolene	495-62-5	207-805-8		<0.1%	SCI 2-SS 1B-AH 1; H304-H315-H317,-
Terpinolene	586-62-9	209-578-0		<0.1%	SS 1B-AH 1-EH A1-EH C1;H304-H317-H410,-
3,7-Dimethyl-1,3,6-octatriene	13877-91-3	237-641-2		<0.1%	FL 3-AH 1;H226-H304, -
Pinenes	UNKNOWN			<0.1%	SCI 2-SS 1B-AH 1-EH A1-EH C1;H304-H315- H317-H410,-

Substances with Community workplace exposure limits:

Name	CAS	EC	%
Butylated hydroxytoluene	128-37-0	204-881-4	<0.1%
Diethyl phthalate	84-66-2	201-550-6	1-<5%
Furfural	98-01-1	202-627-7	<0.1%

Substances that are persistent, bioaccumulative and toxic or very persistent and very bioaccumulative, greater than 0.1%:

Not Applicable

Section 4. First-aid measures

4.1 Description of first aid measures

Inhalation: Remove from exposure site to fresh air, keep at rest, and obtain medical attention.

Eye exposure: Flush immediately with water for at least 15 minutes. Contact physician if symptoms persist.

Skin exposure: Remove contaminated clothes. Wash thoroughly with soap and water. Contact physician if irritation persists.

Ingestion: Rinse mouth with water and obtain medical attention.

4.2 Most important symptoms and effects, both acute and delayed

None expected, see Section 4.1 for further information.

4.3 Indication of any immediate medical attention and special treatment needed

None expected, see Section 4.1 for further information.

SECTION 5: Firefighting measures

5.1 Extinguishing media

Suitable media: Carbon dioxide, Dry chemical, Foam.

5.2 Special hazards arising from the substance or mixture

In case of fire, may be liberated: Carbon monoxide, Unidentified organic compounds.

SAFETY DATA SHEET

In accordance with REACH Regulation EC No.1907/2006

Product: Eastern Illusion INTENSE Candle - Wax Melt 478269CANDLE

Version: 1

5.3 Advice for fire fighters:

In case of insufficient ventilation, wear suitable respiratory equipment.

Section 6. Accidental release measures

6.1 Personal precautions, protective equipment and emergency procedures:

Avoid inhalation. Avoid contact with skin and eyes. See protective measures under Section 7 and 8.

6.2 Environmental precautions:

Keep away from drains, surface and ground water, and soil.

6.3 Methods and material for containment and cleaning up:

Remove ignition sources. Provide adequate ventilation. Avoid excessive inhalation of vapours. Contain spillage immediately by use of sand or inert powder. Dispose of according to local regulations.

6.4 Reference to other sections:

Also refer to sections 8 and 13.

Section 7. Handling and storage

7.1 Precautions for safe handling:

Keep away from heat, sparks, open flames and hot surfaces. - No smoking. Use personal protective equipment as required. Use in accordance with good manufacturing and industrial hygiene practices. Use in areas with adequate ventilation. Do not eat, drink or smoke when using this product.

7.2 Conditions for safe storage, including any incompatibilities:

Store in a well-ventilated place. Keep container tightly closed. Keep cool. Ground/bond container and receiving equipment. Use explosion-proof electrical, ventilating and lighting equipment. Use only non-sparking tools. Take precautionary measures against static discharge.

7.3 Specific end use(s):

AIRCARE: Use in accordance with good manufacturing and industrial hygiene practices.

Section 8. Exposure controls/personal protection

8.1 Control parameters

Workplace exposure limits:

SAFETY DATA SHEET

In accordance with REACH Regulation EC No.1907/2006

Product: Eastern Illusion INTENSE Candle - Wax Melt 478269CANDLE

Version: 1

Ingredient	CAS	EC	Description	Value
Butylated hydroxytoluene	128-37-0	204-881-4	Long-term exposure limit (8-hour TWA) (mg/m3)	10
Diethyl phthalate	84-66-2	201-550-6	Long-term exposure limit (8-hour TWA) (mg/m3)	5
			Short-term exposure limit (15-minute) (mg/m3)	10
Furfural	98-01-1	202-627-7	Long-term exposure limit (8-hour TWA) (ppm)	2
			Long-term exposure limit (8-hour TWA) (mg/m3)	8
			Short-term exposure limit (15-minute) (ppm)	5
			Short-term exposure limit (15-minute) (mg/m3)	20

8.2 Exposure Controls

Eye / Skin Protection

Wear protective gloves/eye protection/face protection

Respiratory Protection

Ensure adequate and ongoing ventilation is maintained in order to prevent build up of excessive vapour and to ensure occupational exposure limits are adhered to. If appropriate, and depending on your patterns and volumes of use, the following engineering controls may be required as additional protective measures: a) Isolate mixing rooms and other areas where this material is used or openly handled. Maintain these areas under negative air pressure relative to the rest of the plant. b) Employ the use of Personal protective equipment - an approved, properly fitted respirator with organic vapour cartridges or canisters and particulate filters. c) Use local exhaust ventilation around open tanks and other open sources of potential exposures in order to avoid excessive inhalation, including places where this material is openly weighed or measured. In addition, use general dilution ventilation of the work area to eliminate or reduce possible worker exposures. d) Use closed systems for transferring and processing this material.

Also refer to Sections 2 and 7.

Section 9. Physical and chemical properties

9.1 Information on basic physical and chemical properties

Appearance:	Not determined
Odour:	Not determined
Odour threshold:	Not determined
pH:	Not determined
Melting point / freezing point:	Not determined
Initial boiling point / range:	Not determined
Flash point:	> 100 °C
Evaporation rate:	Not determined

SAFETY DATA SHEET

In accordance with REACH Regulation EC No.1907/2006

Product: Eastern Illusion INTENSE Candle - Wax Melt 478269CANDLE

Version: 1

Flammability (solid, gas):	Not determined
Upper/lower flammability or explosive limits:	Product does not present an explosion hazard
Vapour pressure:	Not determined
Vapour density:	Not determined
Relative density:	Not determined
Solubility(ies):	Not determined
Partition coefficient: n-octanol/water:	Not determined
Auto-ignition temperature:	Not determined
Decomposition temperature:	Not determined
Viscosity:	Not determined
Explosive properties:	Not expected
Oxidising properties:	Not expected

9.2 Other information: None available

Section 10. Stability and reactivity

10.1 Reactivity:

Presents no significant reactivity hazard, by itself or in contact with water.

10.2 Chemical stability:

Good stability under normal storage conditions.

10.3 Possibility of hazardous reactions:

Not expected under normal conditions of use.

10.4 Conditions to avoid:

Avoid extreme heat.

10.5 Incompatible materials:

Avoid contact with strong acids, alkalis or oxidising agents.

10.6 Hazardous decomposition products:

Not expected.

Section 11. Toxicological information

11.1 Information on toxicological effects

This mixture has not been tested as a whole for health effects. The health effects have been calculated using the methods outlined in Regulation (EC) No 1272/2008 (CLP).

This material does not meet the criteria for classification for health hazards under Regulation (EC) No 1272/2008.

Acute Toxicity: Based on available data the classification criteria are not met.

SAFETY DATA SHEET

In accordance with REACH Regulation EC No.1907/2006

Product: Eastern Illusion INTENSE Candle - Wax Melt 478269CANDLE

Version: 1

Acute Toxicity Oral	Not Applicable
Acute Toxicity Dermal	Not Applicable
Acute Toxicity Inhalation	Not Available
Skin corrosion/irritation:	Based on available data the classification criteria are not met.
Serious eye damage/irritation:	Based on available data the classification criteria are not met.
Respiratory or skin sensitisation:	Based on available data the classification criteria are not met.
Germ cell mutagenicity:	Based on available data the classification criteria are not met.
Carcinogenicity:	Based on available data the classification criteria are not met.
Reproductive toxicity:	Based on available data the classification criteria are not met.
STOT-single exposure:	Based on available data the classification criteria are not met.
STOT-repeated exposure:	Based on available data the classification criteria are not met.
Aspiration hazard:	Based on available data the classification criteria are not met.

Information about hazardous ingredients in the mixture

Not Applicable

Refer to Sections 2 and 3 for additional information.

Section 12. Ecological information

12.1 Toxicity:

Harmful to aquatic life with long lasting effects.

12.2 Persistence and degradability: Not available

12.3 Bioaccumulative potential: Not available

12.4 Mobility in soil: Not available

12.5 Results of PBT and vPvB assessment:

This substance does not meet the PBT/vPvB criteria of REACH, annex XIII.

12.6 Other adverse effects: Not available

Section 13. Disposal considerations

13.1 Waste treatment methods:

Dispose of in accordance with local regulations. Avoid disposing into drainage systems and into the environment. Empty containers should be taken to an approved waste handling site for recycling or disposal.

Section 14. Transport information

14.1 UN number: Not classified

14.2 UN Proper Shipping Name: Not classified

14.3 Transport hazard class(es): Not classified

SAFETY DATA SHEET

In accordance with REACH Regulation EC No.1907/2006

Product: Eastern Illusion INTENSE Candle - Wax Melt 478269CANDLE

Version: 1

Sub Risk: Not classified

14.4. Packing Group: Not classified

14.5 Environmental hazards: Not environmentally hazardous for transport

14.6 Special precautions for user: None additional

14.7 Transport in bulk according to Annex II of MARPOL73/78 and the IBC Code:

Not classified

Section 15. Regulatory information

15.1 Safety, health and environmental regulations/legislation specific for the substance or mixture

None additional

15.2 Chemical Safety Assessment

A Chemical Safety Assessment has not been carried out for this product.

Section 16. Other information

Concentration % Limits: EH C3=12.20%

Total Fractional Values: EH C3=8.20

Key to revisions:

Not applicable

Key to abbreviations:

Abbreviation	Meaning
AH 1	Aspiration Hazard Category 1
ATO 4	Acute Toxicity - Oral Category 4
EDI 2	Eye Damage / Irritation Category 2
EH A1	Hazardous to the Aquatic Environment - Acute Hazard Category 1
EH C1	Hazardous to the Aquatic Environment - Long-term Hazard Category 1
EH C2	Hazardous to the Aquatic Environment - Long-term Hazard Category 2
FL 3	Flammable Liquid, Hazard Category 3
H226	Flammable liquid and vapour.
H302	Harmful if swallowed.
H304	May be fatal if swallowed and enters airways.
H315	Causes skin irritation.
H317	May cause an allergic skin reaction.
H319	Causes serious eye irritation.
H410	Very toxic to aquatic life with long lasting effects.
H411	Toxic to aquatic life with long lasting effects.
P210	Keep away from heat, sparks, open flames and hot surfaces. - No smoking.
P233	Keep container tightly closed.

SAFETY DATA SHEET

In accordance with REACH Regulation EC No.1907/2006

Product: Eastern Illusion INTENSE Candle - Wax Melt 478269CANDLE

Version: 1

P240	Ground/bond container and receiving equipment.
P241	Use explosion-proof electrical, ventilating and lighting equipment.
P242	Use only non-sparking tools.
P243	Take precautionary measures against static discharge.
P261	Avoid breathing vapour or dust.
P264	Wash hands and other contacted skin thoroughly after handling.
P270	Do not eat, drink or smoke when using this product.
P272	Contaminated work clothing should not be allowed out of the workplace.
P273	Avoid release to the environment.
P280	Wear protective gloves/eye protection/face protection.
P301/310	IF SWALLOWED: Immediately call a POISON CENTER or doctor/physician.
P301/312	IF SWALLOWED: call a POISON CENTER or doctor/physician if you feel unwell.
P302/352	IF ON SKIN: Wash with plenty of soap and water.
P303/361/353	IF ON SKIN (or hair): Remove/take off immediately all contaminated clothing. Rinse skin with water/shower.
P305/351/338	IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses, if present and easy to do. Continue rinsing.
P330	Rinse mouth.
P331	Do not induce vomiting.
P332/313	If skin irritation occurs: Get medical advice/attention.
P333/313	If skin irritation or rash occurs: Get medical advice/attention.
P337/313	If eye irritation persists: Get medical advice/attention.
P362	Take off contaminated clothing and wash before reuse.
P363	Wash contaminated clothing before reuse.
P370/378	In case of fire: Use carbon dioxide, dry chemical, foam for extinction.
P391	Collect spillage.
P403/235	Store in a well-ventilated place. Keep cool.
P405	Store locked up.
P501	Dispose of contents/container to approved disposal site, in accordance with local regulations.
SCI 2	Skin Corrosion / Irritation Category 2
SS 1B	Sensitization - Skin Category 1B

The information in this safety data sheet is to the best of our knowledge true and accurate but all data, instructions, recommendations and/or suggestions are made without guarantee.